A. Introduction

ZT100 is a battery-powered, auto-ranging digital multimeter with a 4000 counts. LCD display and backlight. It can be used to measure AC/DC voltage, AC/DC current. resistance, capacitance, frequency, duty cycle, diode, and continuity,

B. Safety Information

To avoid possible electrical shock, fire, or personal injury, please read all safety information before you use the product.

(1) Do NOT exceed the "maximum value" indicated in the Specification. (2) Examine the connection of the test leads and the insulation of the product before measuring voltage higher than 36V DC or 25V AC. (3) Disconnect the test leads from the circuit before changing the mode -(4) Misuse of mode or range can lead to hazards, be cautious. "OL" will be shown on the display when the input is out of range.


(5) Safety symbols:

A	Hazardous Voltage	÷	Earth
	Double Insulated	2	Low Battery
Â	Risk of Danger. Check the User Manual.		

C Specifications

c. specificatio	0115				
		Electrica	al Specifications	5	
Function	Range	Resolution	Accuracy	MAX.Value	Other
DC Voltage	400.0mV	0.1mV		1000V	
	4.000V	0.001V	±(0.5%+4)		
	40.00V	0.01V			
	400.0V	0.1V	L (0,0%(+4)		
	1000V	1V	±(0.8%+4)		
AC Voltage	400.0mV	0.1mV	±(1.2%+4)	750V	
	4.000V	0.001V			40Hz-400Hz
	40.00V	0.01V			
	400.0V	0.1V			
	750V	1V	±(1.5%+4)		
DC Current (A)	4.000A	0.001A	±(1.5%+4)	10A	
	10.00A	0.01A		IUA	
DC Current (mA)	40.00mA	0.01mA		400mA	
	400.0mA	0.1mA			
AC Current (A)	4.000A	0.001A	±(2.0%+4)	10A	
	10.00A	0.01A			40Hz-400Hz
AC Current (mA)	40.00mA	0.01mA		400mA	4002-400HZ
	400.0mA	0.1mA			

Function	Range	Resolution	Accuracy	MAX.Value	Other	
	400.0Ω	0.1Ω				
Resistance	4.000kΩ	0.001kΩ]			
	40.00kΩ	0.01kΩ	±(0.8%+4)	40MO		
	400.0kΩ	0.1kΩ		4010122		
	4.000MΩ	0.001MΩ				
	40.00MΩ	0.01MΩ	±(2.0%+4)			
	4.000nF	0.001nF	± (5.0%+20)	200µF		
Capacitance	40.00nF	0.01nF	±(3.5%+4)			
	400.0nF	0.1nF				
	4.000μF	0.001µF				
	40.00µF	0.01µF	1			
	200.0µF	0.1µF				
	99.99Hz	0.01Hz	1			
	999.9Hz	0.1Hz	1			
Frequency	9.999kHz	0.001kHz	±(0.1%+2)	9.999MHz		
ricquency	99.99kHz	0.01kHz	- (0.1/012)	5.55510112		
	999.9kHz	0.1kHz	1			
	9.999MHz	0.001MHz				
Duty Cycle	1%~99%	0.1%	±(0.1%+2)			
Diode			V			
Continuity			٧			
		General Spe				
Display (LCD)		4000 counts				
Ranging		Auto				
Material		ABS				
Update Rate		3 times/second				
Ture RMS		×				
Data Hold		√				
Backlight		√				
Low Battery		√				
Auto Power	Off		٧			
		Mechanical Sp	pecifications			
Dimension		130*65*32mm				
Weight		130g				
Battery Type		1.5V AAA Battery * 2				
Warranty		One years				
		Environmental	Specifications			
Operating		Temperature 0~40°C				
		Humidity <75%				
Storage		Temperature -20~60°C				
		Humidity <80%				
		Safety Spec	cifications			
			04.2 500 8- + 45	Chupperty 2016		
EN	61010-1: 201	10; EN 61326-1: 2	013; FCC Part 15	SDupart: 2016		
		LU; EN 61326-1: 2 Standard Ad Test Lead * 1 pair	ccessories			



6. 10A: Input terminal for current (A) measurements.

(2) Measure AC/DC Current

- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the VOHz Terminal or the 10A Terminal (choose based on the value of current):
- 2. Turn the rotary switch to the Current-A Mode or the Current-mA Mode: 3. Press SELECT to toggle between AC/DC;
- 4. Break the circuit path to be measured. Then connect the test leads across the break and apply power;
- Read the measured current on the display.
- *Caution:
- a. Do not measure current that exceeds the MAX Value as indicated in the Specifications:
- b. Use the 10A Terminal and the Current-A Mode when you are measureing an unknown current. Then switch to the VQHz Termianl and the Current-mA Mode if necessary.

Do not input voltage exceeds 36V DC or 25V AC when you are at the setting of measuring current.

ZT100 Digital Multimeter User Manual

- 1 -

- 3 -

(3) Measure AC/DC Voltage

- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the V Ω Hz Terminal;
- 2. Turn the rotary switch to the AC Voltage Mode or the DC Voltage Mode;
- 3. Touch the probes to the correct test points of the circuit to measure the voltage;

4. Read the measured voltage on the display.

*Caution:

- a. Do not measure voltage that exceeds the MAX Value as indicated in the Specifications;
- b. Do not touch high voltage circuit during measurements.

(4) Measure Resistance

- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the V Ω Hz Terminal;
- 2. Turn the rotary switch to the Resistance Mode, and the display will show "OL";
- Touch the probes to the desired test points of the circuit to measure the resistance;
- 4. Read the measured resistance on the display.
- *Caution:
- a. Disconnect circuit power and discharge all capacitors before you test resistance.
- b. Do not input voltage at the Resistance Mode.

(5) Measure Diode

- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the V Ω Hz Terminal;
- Turn the rotary switch to the Resistance Mode, press SELECT once to toggle to the Diode Mode;
- Connect the red probe to the anode side and the black probe to the cathode side of the diode being tested;
- 4. Read the forward bias voltage value on the display;
- If the polarity of the test leads is reversed with diode polarity or the diode is broken, the display reading shows "OL".

*Caution:

- a. Do not input voltage at the Diode Mode.
- b. Disconnect circuit power and discharge all capacitors before you test diode.

(6) Measure Continuity

- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the V Ω Hz Terminal;
- 2. Turn the rotary switch to the Resistance Mode, press SELECT twice to toggle to the Continuity Mode;
- 3. Touch the probes to the desired test points of the circuit;
- 4. The built-in beeper will beep when the resistance is lower than $50\Omega,$ which indicates a short circuit.

*Caution:

a. Do not input voltage at the Continuity Mode

- (7) Measure Capacitance
- 1. Connect the black test lead to the COM Terminal and connect the red test lead to the V Ω Hz Terminal;
- Turn the rotary switch to the Resistance Mode, press SELECT three times to toggle to the Capacitance Mode;
- Connect the red probe to the anode side and the black probe to the cathode side of the capacitor being tested;
- 4. Read the measured capacitance value on the display once the reading is stablized. *Caution:
- a. Disconnect circuit power and discharge all capacitors before you test capacitance.

(8) Measure Frequency and Duty Cycle

- Connect the black test lead to the COM Terminal and connect the red test lead to the VΩHz Terminal;
- Turn the rotary switch to the Frequency Mode; press SELECT once to toggle to the Duty Cycle Mode if you want to measure duty cycle;
- 3. Touch the probes to the desired test points of the circuit;
- 4. Read the measured frequency/duty cycle value on the display.
- *Caution:
- a. The Frequency Mode only applies to measure high frequency with low voltage

(9) Auto Power Off

- 1. The product automatically powers off after 15 minutes of inactivity;
- 2. The built-in beeper beeps 5 times 1 minute before power off;
- 3. To restart the product, press SELECT botton;
- To disable the Auto Power Off function, hold down the SELECT botton when turning on the product, you will hear five beeps if you have successfully disabled the function.

E. Genearl Maintenance

- Beyond replacing batteries and fuses, do not attempt to repair or service the product unless you are qualified to do so and have the relevant calibration, performance test, and service instructions.
- (1) Do not operate the product around hot, wet, flammable, explosive or magnetic environments.
- (2) Clean the product with damp cloth and mild detergent; do not use abrasives or solvents.
- (3) Remove the input signals before you clean the product.
- (4) Remove the batteries if you will not use the product for a long time to prevent possible battery leak.
- (5) When "
 ⁽⁵⁾ is shown on the display, batteries shall be replaced as below: 1. Loosen the screw and remove the battery cover;
- 2. Replace the used batteries with new batteries of the same type;
- 3. Place the battery cover back and fasten the screw.
- (6) Replace fuses as above steps. Use only fuses of the same type as the original
 - ones.

Warning:

- 1. Do NOT exceed the "maximum value" indicated in the Specification;
- 2. Do NOT input voltage at the Current Mode, the Resistance Mode, the Diode Mode. or the Continuity Mode:
- 3. Do NOT use the product when the batteries or the battery cover is not placed
- properly;
- 4. Turn off the product and remove the test leads from the test points before changing batteries or fuses.

F. Troubleshooting

If your product do not function as normal, the following steps may help you. If the problem still cannot be solved, please contact your dealer.

Problem	Possible Reason
Display Mulfunction	Low battery; replace batteries
🖞 Symbol	Replace batteries
No current input	Replace fuse

LIMITED WARRANTY AND LIMITATION OF LIABILITY

Customers enjoy one-year warranty from the date of purchase. This warranty does not cover fuses, disposable batteries, or damage from accident, neglect, misuse, alternation, contamination, or abnormal conditions of operation or handling.

All rights reserved. Specifications are subject to change without notice

- 6 -

- 7 -