

Value⁺



WT26

Series

Manual

The Value+ Model WT26A, WT26B and WT26C Cable Length Meter (the meter) is for:

- measuring the length of cables including network cables, phone lines and BNC cables;
- tracing cables (by digital or analogue signals);
- testing cables.

The meter also designed for using on PoE-capable devices to help to minimize the workload of users.

With careful use, the meter will provide years of reliable service.



TABLE OF CONTENT

Read Before Use – Safety Information	1
The Equipment	2
Main Body	2
Receiver	3
LCD Display	3
Push Buttons	4
Operating the Equipment	4
A. Cable Length Measurement	4
B. Tracing Cables	6
C. Testing Cables	9
Auto Power Off	10
Specification	11
Maintenance	12
Charging	12
Changing Battery for Main Body	12
Changing Battery for Receiver	13
Cleaning	13

READ BEFORE USE – SAFETY INFORMATION


WARNING

To ensure safety operation and service of the equipment, please follow these guidelines:

- Do not use the equipment just before, during or just after an electrical storm (electrical shock / high energy overvoltage!). Please make sure that your hands, your shoes, your clothing, the floor, switches and switching components are dry.
 - Trace only unenergized wiring. Contact with live circuits can result in severe injury or death.
 - Do not use the equipment and/or the accessory if they look damaged and / or wet.
 - Never use the equipment if it just brought from a place with great temperature difference.
 - Do not use the equipment around explosive gas or vapor.
 - Avoid to use the equipment in the environment with strong magnetic fields, strong electrostatic fields and strong RF fields.
 - Read the instruction before use and follow all safety instructions.
 - Use the equipment only as specified in the instruction card; otherwise, the equipment's safety features may not protect you.
 - Remove the batteries if the equipment planned to be stored for long period.
 - Personal injury or damage to the equipment can occur if you attempt to make a measurement with a lead in an incorrect terminal.
-
- A " **Warning**" statement identifies hazardous conditions and actions that could cause bodily harm or death.
 - A " **Caution**" statement identifies conditions and actions that could damage the equipment or the object under test.


THE EQUIPMENT

MAIN BODY




- | | |
|----------------------|-----------------------------|
| 1) USB charging jack | 5) RJ11 cable jack |
| 2) LCD display | 6) Loopback RJ45 cable jack |
| 3) Push buttons | 7) Main cable RJ45 jack |
| 4) BNC cable jack | |

RECEIVER




- 1) RJ45 Connector
- 2) Indicators
- 3) Cable Tracing Button
- 4) Flashlight Switch
- 5) Scan Ready Indicator
- 6) Flashlight
- 7) Volume Adjusting Wheel
- 8) Tracing Probe
- 9) Battery Door

LCD DISPLAY




- | | |
|----------------------------|---|
| 1) Short Circuit Indicator | 9) Unit of the Primary Display (Meter) |
| 2) Cable Testing Indicator | 10) Ready for Wire Tracking |
| 3) No. of Pairs Indicator | 11) Secondary Display |
| 4) Warning Symbol | 12) Ready for Measuring Length or Cable Testing |
| 5) Ready for Phone Line | 13) Receiver Sound On Indicator |
| 6) Ready for BNC Cable | 14) Battery Indicator |
| 7) Ready for Network Cable | |
| 8) Primary Display | |

PUSH BUTTONS




Button	Mode	Function	Access
 MODE	Power off	Switch on the meter	Press to switch on the meter
	Any	Switch off the meter	Hold down about 3 seconds to switch on and off
	Any	Switch between cable length measurement, cable tracing and cable testing	Press once to switch to next functions
▲ ▼	Cable Length Measurement	Switch to check different pair of wires	Press either button to switch
▲	Cable Tracing	Switch between digital and analogue	Press to switch
PORT	Cable Length and Cable Tracing	Switch to select network cable, phone line and BNC cable	Press to switch

OPERATING THE EQUIPMENT



A. CABLE LENGTH MEASUREMENT

Switch on the main body by pressing the  button. The Main Body will be ready for measuring the cable length.



To check the network cable:

- 1) The main body will be ready for measuring network cable length when it is switch on;
- 2) Check if  appears, go to point 3. Otherwise, press “PORT” button until  appears and go to point 3;
- 3) Unplug all cables which is connected to the main body;
- 4) Plug the testing network cable to the **LOOPBACK** plug;
- 5) The cable length will be automatically display;
- 6) After measuring, switch off the main body by holding down the  button for about 3 seconds.



Note:

-  and  will be displayed if the measuring cable is short circuit. In the meantime, the meter will also display the pair of wires which is short at the secondary display.



To check the phone line (WT26B/C):

- 1) Unplug all the cables connected to the main body;
- 2) Select the phone line mode by pressing the “**PORT**” button until the  appears;
- 3) Plug the phone line need to be tested to the **RJ11** jack at the top of the main body;
- 4) The cable length will be automatically display;
- 5) After measuring, switch off the main body by holding down the  button for about 3 seconds.



Note:

-  and  will be displayed if the measuring cable is short circuit. In the meantime, the meter will also display the pair of wires which is short at the secondary display.


To check the BNC cable (WT26B/C):

- 1) Unplug all the cables connected to the main body;
- 2) Press “**PORT**” button to select the BNC cable measuring mode. When it is ready for BNC cable measuring, the  appears;
- 3) Plug the testing cable to be measured to the **BNC** jack at the top of the main body;
- 4) The cable length will be automatically display;
- 5) After measuring, switch off the main body by holding down the  button for about 3 seconds.







Note:

-  and  will be displayed if the measuring cable is short circuit. In the meantime, the meter will also display the pair of wires which is short at the secondary display.



B. TRACING CABLES

Switch on the main body by pressing the  button. Press the **"MODE"** button again to select the cable tracing function. **"WireTracker"** will be appeared when the meter is ready for tracing cables.



Network cable tracing:

- 1) The main body is ready for tracing the network cable by analogue signal and both  and **"-1-"** will be appeared to indicate the main body is ready for this function;
- 2) If needed, users are allowed to select:
 - a) digital signal by press   to select. When the equipment is ready for sending digital signal, the display will show **"-2-"**; or
 - b) another analogue signal by press   to select. When the equipment is ready for sending the second analogue signal, the display will show **"-3-"**;
- 3) Plug the network cable to be tracked in the **MAIN** jack;
- 4) Hold down the **"SCAN"** button on the receiver to switch on the receiver;
- 5) Press the **"SCAN"** button to select digital and analogue signal;
 - a) Blue indicator will switch on when the receiver is ready for receiving digital signal with sound indication;
 - b) Blue indicator flashing when the receiver is ready for receiving digital signal with vibrating indication; or
 - c) Red indicator will witch when the receiver is ready for receiving analogue signal with sound indication;
- 6) Move the receiver close to each of the unknown cables. When the receiver is closed to the cable which is plug in the Main Body at the other side,
 - a) largest sound will be heard if blue or red indicator on the receiver is on; or
 - b) largest vibration will be obtained if blue indicator on the receiver is flashing.
- 7) After tracing, switch off the Main Body by holding down the  button for 3 seconds;
- 8) Also switch off the receiver by holding down the **"SCAN"** button for 3 seconds.




Phone Line tracing (WT26B/C):

- 1) Select the phone line tracing mode by pressing the "PORT" button until  appears;
- 2) Select analogue or digital signal for tracing by pressing ▲ or ▼;
 - a) When display showing "-1-" or "-3-", the equipment is sending analogue signal for tracing;
 - b) When display showing "-2-", the equipment is sending digital signal for tracing;
- 3) Hold down the **"SCAN"** button on the receiver to switch on the receiver;
- 4) Select analogue or digital signal for tracing by pressing the **"SCAN"** button,
 - a) Blue indicator will switch on when the receiver is ready for receiving digital signal with sound indication;
 - b) Blue indicator flashing when the receiver is ready for receiving digital signal with vibrating indication; or
 - c) Red indicator will switch on when the receiver is ready for receiving analogue signal with sound indication;
- 5) Move the receiver close to each of the unknown lines. When the receiver is closed to the cable which is plug in the Main Body at the other side,
 - a) largest sound will be heard if blue or red indicator on the receiver is on; or
 - b) largest vibration will be obtained if blue indicator on the receiver is flashing.
- 6) After tracing, switch off the Main Body by holding down the  button for 3 seconds;
- 7) Also switch off the receiver by holding down the "SCAN" button for 3 seconds.

BNC cable tracing (WT26B/C):

- 1) Select the BNC cable tracing mode by press the “**PORT**” button until  appears;
- 2) Select analogue or digital signal for tracing by pressing ▲ or ▼;
 - a) When display showing “-1-” or “-3-”, the equipment is sending analogue signal for tracing;
 - b) When display showing “-2-”, the equipment is sending digital signal for tracing;
- 3) Hold down the “SCAN” button on the receiver to switch on the receiver;
- 4) Select analogue or digital signal for tracing by pressing the “**SCAN**” button,
 - a) Blue indicator will switch on when the receiver is ready for receiving digital signal with sound indication;
 - b) Blue indicator flashing when the receiver is ready for receiving digital signal with vibrating indication; or
 - c) Red indicator will witch when the receiver is ready for receiving analogue signal with sound indication;
- 5) Move the receiver close to each of the unknown cables. When the receiver is closed to the cable which is plug in the Main Body at the other side,
 - a) largest sound will be heard if blue or red indicator on the receiver is on; or
 - b) largest vibration will be obtained if blue indicator on the receiver is flashing.
- 6) After tracing, switch off the Main Body by holding down the  button for 3 seconds;
- 7) Also switch off the receiver by holding down the “**SCAN**” button for 3 seconds.


C. TESTING CABLES

Switch on the main body by pressing the  button. Press the  button again to select the Cable Testing function. When the Main Body is ready for Cable Testing, --- and  appears on the primary display.


Users are allowed to perform test by either connect both side of the testing cable to **MAIN** and **LOOPBACK** jack; or connect one side to **LOOPBACK** and the other side to the **RJ45** jack on the receiver.

For connecting to **MAIN** and **LOOPBACK**,


- 1) Unplug all the cable(s) connected;
 - 2) Plug the testing cable to the **MAIN** and **LOOPBACK** jacks;
 - 3) The cable connection status will be display on the secondary display.
- 4) The display will be shown as right, if the connection is correct.




- 5) If any cable is opened, the corresponding number at the upper part will not appear. For example, if the display show as right, it means that line 6 and line 7 are opened.




- 6) If any set(s) of wire are short, only the shorted pair of wires will be shown. For example, if the display is shown as right, it means that line 1 and 2 are short.



- 7) If more than one pair of wires are shorted, the meter will show the shorted pair one by one.
- 8) After testing, switch off the Main Body by holding down the  button for 3 seconds.

For connecting to the **LOOPBACK** and the **RJ45** jack on the receiver,

- 1) Unplug all the cable(s) connected to the main body and receiver;
- 2) Plug one side of the testing cable to the **LOOPBACK** jack on the Main Body and the other side to the **RJ45** on the receiver;
- 3) The upper part of the secondary display will move from 1 to 8, and the corresponding LED on the receiver will also be switched on;
- 4) If the connection is correct, the number showing on the Main Body will be matched with the LED on the receiver;
- 5) Otherwise, the connection is incorrect.
- 6) After tracing, switch off the Main Body by holding down the  button for 3 seconds;
- 7) There is no need to switch off the receiver.

AUTO POWER OFF

The equipment will automatically switch off if there is no function or button press for 30 minutes.

SPECIFICATIONS

Temperature	Operating: 0°C ~ 40°C Storage: -10°C ~ 50°C
Relative Humidity	<90%
Battery	Main Body: 1 x 3.7V 14500 Lithium (Charging at DC 5V) Receiver: 9V (6F22)
Size	Main Body: 173 x 87 x 37mm Receiver: 35 x 187 x 29mm
Weight	Main Body: 680g (include battery) Receiver: 102g (include battery)

	WT26A	WT26B	WT26C
Basic Functions			
Cable Length Measurement			
2~200m	±(3%+30)	±(3%+30)	±(3%+30)
201~300m	±(3%+3)	±(3%+3)	±(3%+3)
Intelligent Wiremap			
Shorts	✓	✓	✓
Split pairs	✓	✓	✓
Length of Network Cable	✓	✓	✓
Length of Phone Cable		✓	✓
Length of TV Cable		✓	✓
Analogue Cable Tracing			
Digital Cable Tracing			✓
Special Features			
Max display	1999	1999	1999
Display backlight	✓	✓	✓
Low power indication	✓	✓	✓
Auto power off	✓	✓	✓

MAINTENANCE

CHARGING



Caution

Users are allowed to charge the batteries in the Main Body only. To protect the user and the equipment, remove all connections during charging.

Please charge the main body if the battery indicator is flashing. To charge the Main Body, connect the transformer provided to the charger jack and AC wall outlet.

CHANGING BATTERY FOR MAIN BODY



Warning

To avoid shock, injury, or damage to the equipment, remove all the connections from the device before opening the battery doors.

If charging to the main body is not effective, the rechargeable batteries inside come to the end of life. The batteries are needed to be replaced.

To replace the batteries, switch off the main body. Open the equipment by removing the screws at the back of the equipment. Replace the battery pack inside.



Caution

It is recommended to purchase the battery pack from our representative. Using battery pack from other sources may damage the equipment and warranty will be void immediately.

CHANGING BATTERY FOR RECEIVER

Replace the battery for the receiver if the power indicator cannot be switched on when “**SCAN**” button is holding down for more than 3 seconds.

Open the battery door and replace the 9V battery inside, as shown in the photo at the right.



CLEANING



Caution

To avoid damaging the equipment, **NEVER** submerge them in water. **DO NOT** use abrasive cleaners, they will damage the case.

Wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents. Dirt or moisture in the jacks can affect the measurement.

WT26 Series Manual
Version 1.0

Copyright © 2017
All Rights Reserved

Futronix Co.

609 Lee On Building
70 Hung To Road, Kwun Tong
Kowloon, HONG KONG
Tel : (852) 3580 7725
Fax : (852) 3753 4800