

K 5174 & K 5175 Toslink-S/PDIF Converter Kits Errata

K 5175 – Errata

To install TOSLINK Fibre optic transmitter (Altronics Part No. Z 1603) in the K.5175A PCB, The two support pins closest to the front of the unit must be bent outwards slightly to match the existing PCB holes.

